



- STURDY
- LIGHTWEIGHT
- EASY ASSEMBLY

The diagram below will help you set up your counter correctly.

Pop up counters are extremely popular for product launches and trade shows, giving you an instant presentation counter. Simple to set up and transport.

Artwork Template:

Comes complete with two carry bags.

Toolomm Toolomm Pop Up Counter Add 20 - 30mm bleed on all sides x2 Carry Bags Side Front Side

Assembled Dimensions

Width 1300mm • Height: 960mm • Depth: 400mm

Pop Up Counter Frame Assembly Instructions

Contents

- x1 Collapsible Frame
- Supports with double magnetised strips
- x10 straight supports (vertical support)
- x4 slightly curved supports (horizontal support)
- x4 curved supports (horizontal support)
- x6 long curved supports (horizontal support)
- Polythene PVC backing sheet

Magnetic tape



Step 1

Expand collapsible frame.



Step 2

Push together to make hooks catch.



Step 3

Frame is now stable.



Step 4

Starting at the front in the middle at the bottom, begin inserting the vertical strips. First put the pointed end into the connector, then slide the top into the groove.



Step 5

Continue until you have positioned all vertical supports.

It is not necessary to place them at the back in the middle.

For more help email: info@cg.co.nz or phone: (03) 963 8899